

**FITNESS CERTIFICATE  
TO BE FILLED BY THE INSPECTING OFFICER  
(Assistant Engineer)**

1 Name of Officer : Anju Antony  
 2 Location : Alangad  
 3 Name of school : Alhuda Public School, Panayikulam

4 Classification of Building as Specified in column 4 of the application for fitness certificate and size :  
 1. 40.90 x 8.40 x 3.30 m(G.F)  
 2. 40.90 x 8.40 x 3.30 m(F.F)  
 3. 49.70 x 8.20 x 3.30 m(G.F)  
 4. 49.70 x 8.20 x 3.30 m(F.F)

5 Period for which the certificate is issued : 2025-26

6 Nature of Defect if any: :  
 a) Foundation and basement :  
 b) Superstructure :  
 c) Doors and windows : NIL  
 d) Woodwork wrought and put up :  
 e) Flooring :  
 f) Miscellaneous :

7 Any major defects noticed which will render the building unsafe in any manner : NIL  
 Whether maintenance work have been done properly : N/A

9 Whether the structure is sound or not for Conducting classes : Yes Sound under normal weather conditions

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind exposure of flood etc.  
 2. Any additional observation deemed necessary for the certificate may be furnished separately with the certificate.


Certified that the school was inspected by me on 29/05/2025 and found to be fit for the period for there as on stated above.


Place: Alangad

Signature: 


Date: 29/05/2025

Designation: Assistant Engineer

  
 MANAGER  
 ALHUDA PUBLIC SCHOOL  
 PANAYIKULAM-683 511



ASSISTANT ENGINEER  
 LID & EW  
 ALANGAD GRAMA PANCHAYAT  
 PIN-683 511

  
 PRINCIPAL  
 alhuda Public School  
 PANAYIKULAM


## FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

1. Name of Officer : Anu T. Asst. Exe. Engineer,  
L S G D Sub Division, Alangad BP
2. Name of School : ALHUDA PUBLIC SCHOOL
3. Location with name of Education : Ward 12, Panayikulam, Alangad GP
4. District, Sub-District : Aluva, Emakulam
5. Classification of buildings as specified in column 4 of application for Fitness Certificate and Size : Permanent
- Auditorium - 1No. (24.44 X 10.24 X 9.28 M)  
Kinder Garden -GF- 2 No (5.25 X 6.9 X 9.28 M) RCC  
FF- 2 No (5.25 X 6.9 X 9.28 M)  
Old Block- class room GF- 2 No (6.46 X 6 X 3.99 M)  
Administration Room 1No (6.46 X 3.64 X 3.99 M)  
Staff room . (5.03 X 4.24 X 3.00 M) RCC
6. Period for which the certificate is issued : 2025-26
7. Nature of defect if any
- a) Foundation and basement : Nil
- b) Superstructure : Nil
- c) Doors and Windows : Nil
- d) Wood work wrought & put up : Nil
- e) Roof : Nil
- f) Flooring : Nil
- g) Miscellaneous (Cracks etc.) : Nil
8. Any major defects noticed which will render the building unsafe in any manner : No
9. Whether the maintenance works have been properly supervised by the LSGD : No
10. Whether the structure is sound or not for conducting classes : Yes, under normal weather condition


Certified that the school was inspected by me on 15.11.2025 and found to be fit to conduct classes for the period 2025-26 for the reasons stated above.

Place: Alangad

Date: 22.11.2025

  
MANAGER  
ALHUDA PUBLIC SCHOOL  
PANAYIKULAM-683 511



Signature 

Designation: ANU T.

PEN: 701830

ASSISTANT EXECUTIVE ENGINEER  
LID & EW SUB DIVISION  
BLOCK PANCHAYATH, ALANGAD

  
PRINCIPAL  
alhuda Public School  
PANAYIKULAM